

glenngraphics

COPYRIGHT

# WELDING/CUTTING SAFETY



★ WEAR PROPER EYE/FACE PROTECTION.

★ WEAR FIRE RESISTANT GLOVES AND CLOTHING FREE OF OIL AND GREASE.

## PERSONNEL PROTECTION

USE FALL PROTECTION.

PLACE EQUIPMENT AS TO PREVENT TRIPPING.

USE PROPER EYE AND FACE PROTECTORS.

USE FIRE RESISTANT GLOVES AND CLOTHING.

PROTECT ADJACENT WORKERS WITH NON-COMBUSTIBLE BOOTHS AND SCREENS.

★ PROTECT COMBUSTIBLES WITHIN 25 FEET OF WORK AREA, AND HAVE FIRE EXTINGUISHERS AVAILABLE!



ORDER #GG120

SAMPLE

glenngraphics

COPYRIGHT